

MANUFACTURER SERVICE BULLETINS / LETTERS COMPLIANCE RECORD

Year: N315EN LH prop. HC-C3YR-2UF S/N CK4093A TSOH: 0.0 HOBBS: 3185.2
Date: 4-21-2017

Date: Propeller removed and OH'd during engine replacement, Installed OH'd prop IAW
maintenance manual, torqued nuts to 70ft/lb. and safetied, test run and leak check
Next successful.


Due: Steele Aerospace Services
Steele A. Sensintaffar
A+P 3582404 IA



Signature: N315EN LH Propeller HC-C3YR-2UF S/N CK4093A TSOH: 66.4 Hobbs: 3251.4 Date: 1-5-2018

Year: Inspected and serviced Propeller IAW checklist provided by the manufacturer, dressed blades, checked accumulator
pressure, All applicable AD's complied with to this date, I certify this Propeller to comply with the annual inspection
checklist, and was determined to be in an airworthy condition on this date: 1-5-18.

Date: Steele Aerospace Services
Next: Steele A. Sensintaffar
Due: A+P 3582404 IA



Signature: