

8-25-2014 HM 9055.4  
act# 9055.4  
TSPOH 0.0 hrs

Installed prop in Rt position  
N483TC IAW C-414 mm. Ran and  
leak checked OK

I CERTIFY THAT THIS PROPELLER HAS BEEN  
INSPECTED IN ACCORDANCE WITH AN  
ANNUAL INSPECTION AND WAS DETERMINED  
TO BE IN AIRWORTHY CONDITION.

James Hanger IA 3322759

22 Sept 15 9238.1 125.8

Ran and Spinner & Hub For cracks, ckd  
Prop Hub For condition & Dressed Blade &  
Reinstall Spinner & Prop Device.  
Allygen ckd OK at this time.

DATE 22 Sept 15 TAOH HOBBS 9238.1  
I CERTIFY THAT THIS Prop HAS BEEN  
INSPECTED IN ACCORDANCE WITH ADP  
INSPECTION AND WAS DETERMINED TO BE IN  
AIRWORTHY CONDITION AND WAS RETURNED TO  
SERVICE 3400976 TA  
Philip O. Brecher BrenAir Inc.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				

**Aero Valley LLC.** *Right*

**Date: 10/11/2016**      **Reg: N4237C**  
**Hobbs: 9260.7**      **TSPOH: 184.4**

Removed spinner and inspected for cracks. checked hub and blades. Dressed all blades. Reinstalled spinner. A.D. 2006-24-07 N/A. I Certify that this Prop has been inspected in accordance with a 100 hour inspection and has been found to be in airworthy condition at this date and time.  
 Joe Dudley A&P003389126

*Joe Dudley*



Registration:	N4237C	Model:	414	Date:	2-1-2017
S/N:	414-0535	TTAF:	9319.7	Hobbs/Tach:	9319.7
Right Prop S/N:	McCauley 3AF32C515	Prop Model	3AF32C515	Prop TTSMO:	243.4

Complied with an Annual Inspection in reference to the manufactures service manual and required checklist. Checked the prop tracking and inspected the spinner and back plate for damage and security. No new ADs issued at this time. I certify that the maintenance described above, has been accomplished in accordance with Annual inspection and was found to be in an Airworthy condition.

Brian Butler *Brian Butler* A&P IA 2665413



Registration:	N4237C	Model:	414	Date:	11-6-2018
S/N:	414-0535	TTAF:	9331.8	Hobbs/Tach:	9331.8
Right Prop S/N:	McCauley 970736	Prop Model	3AF32C515	Prop TTSMO:	255.57

Complied with an Annual Inspection in reference to the manufactures service manual and required checklist. Checked the prop tracking and inspected the spinner and back plate for damage and security. No new ADs issued at this time. I certify that the maintenance described above, has been accomplished in accordance with Annual inspection and was found to be in an Airworthy condition.

Brian Butler *Brian Butler* A&P IA 2665413

SUB-TOTALS this page

